


Fitting the CAM (Turning) Motor to a Nice Ice N25, N50, N80.

When fitting this motor you will need to use the spacers (circled in red) provided to align the hole in the motor shaft to the hole in the CAM wheel bracket.



Ensure that the centre of the shaft is in the centre of the support bracket hole so that the CAM wheel activates the microswitch correctly.

